

May 26, 2021

Mr. Pat Quinn
Chautauqua Lake Central School District
Business Administrator
100 North Erie Street
Mayville, New York 14757

RECEIVED
JUN 02 2021

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Quinn:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Chautauqua Lake Central School District, including:

- Chautauqua Lake CSD – 100 North Erie Street, Mayville, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on April 1, 2021. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 (*Executive Summary*) of the accompanying report, based upon the sampling and analysis performed, 18 sources of potable water in Chautauqua Lake CSD have been identified as having lead concentrations in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Chautauqua Lake Central School District.

Sincerely,
Stohl Environmental, LLC.



Eric Henderson Jr.
Senior Project Manager

**Investigation and Sampling
Of Sources of Potable Water
For Lead Concentrations**

Prepared for:

Chautauqua Lake Central School District

Prepared by:



**3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM**

Conditions as of April 1, 2021

Summary Tabulation

Lead in Drinking Water Investigation

- 1.1. Scope of Work and Sampling Protocol
- 1.2. Executive Summary of Sampling and Analysis
- 1.3. Response Actions Required Under NYS Regulations
- 1.4. Laboratory Analytical Reports by Building
- 1.5. Laboratory Certifications
- 1.6. Chains of Custody

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by the Chautauqua Lake Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- Chautauqua Lake CSD – 100 North Erie Street, Mayville, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within Chautauqua Lake CSD. Outlets are defined in NYS regulations as: “a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets”.

Sampling Protocol:

In accordance with NYS regulations, *Subpart 67-4: Lead Testing in School Drinking Water*, and the EPA guidance document, *‘3Ts for Reducing Lead in Drinking Water in Schools’*, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.
- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Chautauqua Lake CSD	4/1/2021	183	165	18	N/A	N/A

** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
142.1-86	Men's Room – Left Sink (Btwn B206 & B217)	Sink	27.6
142.1-95	Room B219	Sink	36.6
142.1-99	Room B221	Sink	48.2
142.1-101	Room B222	Sink	39.1
142.1-103	Room B223	Sink	16.7
142.1-105	Room B224	Sink	21.7
142.1-107	Boys Bathroom – Center Sink (Btwn B224 & B232)	Sink	21.5
142.1-114	Room B232	Sink	15.7
142.1-120	Room B237	Sink	16.0
142.1-122	Room B238	Sink	18.9
142.1-173	Room B137 Left Sink	Sink	36.2
142.1-213	Room A138 Small Sink	Sink	28.9
142.1-226	Kitchen Dishwasher Faucet – Left Sink	Sink	32.3
142.1-238	Boys Locker Room – Center Sink	Sink	46.7
142.1-258	Boys Locker Room – Left Sink	Sink	16.0
142.1-265	Ice Machine	Sink	16.2
142.1-300	Girls Bathroom – Left Center Sink	Sink	17.6
142.1-312	Women's Room – Left Sink	Sink	19.2

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

- (a) Prohibit use of the outlet until:
 - (1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and
 - (2) test results indicate that the lead levels are at or below the action level;
- (b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;
- (c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and
- (d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

1.4 Laboratory Analytical Reports by Building



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Report Number: 21-04-00778

Received Date: 04/06/2021
Reported Date: 05/04/2021
Sampled By: Andrew Theal
Tech Certification #:

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N Erie St; Mayville, NY
14757

Client Number:
33-5980

Laboratory Results

Fax Number:
716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-001	142.1-4	04/01/2021	ROOM 266 KITCHEN SINK	6.08	05/03/2021	
21-04-00778-002	142.1-5	04/01/2021	ROOM 268 KITCHEN SINK	5.03	05/03/2021	
21-04-00778-003	142.1-6	04/01/2021	ROOM 268 RIGHT SINK	4.03	05/03/2021	
21-04-00778-004	142.1-7	04/01/2021	FACULTY RESTROOM ALL GENDER BATHROOM	4.40	05/03/2021	
21-04-00778-005	142.1-10	04/01/2021	GIRLS BATHROOM LEFT SINK	1.04	05/03/2021	
21-04-00778-006	142.1-11	04/01/2021	GIRLS BATHROOM CENTER LEFT SINK	2.54	05/03/2021	
21-04-00778-007	142.1-12	04/01/2021	GIRLS BATHROOM CENTER RIGHT SINK	6.76	05/03/2021	
21-04-00778-008	142.1-13	04/01/2021	GIRLS BATHROOM RIGHT SINK	6.62	05/03/2021	
21-04-00778-009	142.1-15	04/01/2021	BOYS BATHROOM LEFT SINK	3.65	05/03/2021	
21-04-00778-010	142.1-16	04/01/2021	BOYS BATHROOM CENTER SINK	1.94	05/03/2021	
21-04-00778-011	142.1-17	04/01/2021	BOYS BATHROOM RIGHT SINK	1.41	05/03/2021	
21-04-00778-012	142.1-18	04/01/2021	ROOM 224 ISLAND SINK	<1.00	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-013	142.1-19	04/01/2021	ROOM 224 LEFT SINK	3.12	05/03/2021	
21-04-00778-014	142.1-20	04/01/2021	ROOM 224 CENTER SINK	3.31	05/03/2021	
21-04-00778-015	142.1-21	04/01/2021	ROOM 224 RIGHT SINK	1.81	05/03/2021	
21-04-00778-016	142.1-22	04/01/2021	GIRLS BATHROOM LEFT SINK	1.61	05/03/2021	
21-04-00778-017	142.1-23	04/01/2021	GIRLS BATHROOM RIGHT SINK	1.60	05/03/2021	
21-04-00778-018	142.1-24B	04/01/2021	BOTTLE FILLER	<1.00	05/03/2021	
21-04-00778-019	142.1-25	04/01/2021	BOYS BATHROOM	<1.00	05/03/2021	
21-04-00778-020	142.1-26	04/01/2021	BOYS BATHROOM	1.82	05/03/2021	
21-04-00778-021	142.1-29	04/01/2021	ROOM 206 SMALL ROOM	5.02	05/03/2021	
21-04-00778-022	142.1-30	04/01/2021	ROOM 207 WALL SINK	3.39	05/03/2021	
21-04-00778-023	142.1-43	04/01/2021	ROOM 208 SMALL ROOM	6.53	05/03/2021	
21-04-00778-024	142.1-44	04/01/2021	ROOM 208 WALL SINK	5.79	05/03/2021	
21-04-00778-025	142.1-61	04/01/2021	ROOM C 210 LEFT SINK	4.27	05/03/2021	
21-04-00778-026	142.1-62	04/01/2021	ROOM C 210 RIGHT SINK	3.80	05/03/2021	
21-04-00778-027	142.1-63	04/01/2021	ROOM A201E	6.54	05/03/2021	
21-04-00778-028	142.1-63B	04/01/2021	ROOM 201E SINK BOTTLE FILLER	<1.00	05/03/2021	
21-04-00778-029	142.1-65	04/01/2021	MENS ROOM LEFT SINK	11.9	05/03/2021	
21-04-00778-030	142.1-66	04/01/2021	MENS ROOM CENTER SINK	1.05	05/03/2021	
21-04-00778-031	142.1-67	04/01/2021	MENS ROOM RIGHT SINK	1.25	05/03/2021	
21-04-00778-032	142.1-68	04/01/2021	WOMENS ROOM LEFT SINK	1.96	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980
 Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
 Erie St; Mayville, NY 14757

Report Number: 21-04-00778

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-033	142.1-69	04/01/2021	WOMENS ROOM CENTER SINK	<1.00	05/03/2021	
21-04-00778-034	142.1-70	04/01/2021	WOMENS ROOM RIGHT SINK	3.18	05/03/2021	
21-04-00778-035	142.1-72	04/01/2021	ROOM A217 BATHROOM	1.30	05/03/2021	
21-04-00778-036	142.1-73	04/01/2021	ROOM A217 SINK	1.75	05/03/2021	
21-04-00778-037	142.1-74	04/01/2021	ROOM A217E SINK	2.20	05/03/2021	
21-04-00778-038	142.1-75	04/01/2021	ROOM B210 LEFT SINK	<1.00	05/03/2021	
21-04-00778-039	142.1-76	04/01/2021	ROOM B210 RIGHT SINK	<1.00	05/03/2021	
21-04-00778-040	142.1-78	04/01/2021	ROOM B209	<1.00	05/03/2021	
21-04-00778-041	142.1-80	04/01/2021	ROOM B208	<1.00	05/03/2021	
21-04-00778-042	142.1-82	04/01/2021	ROOM B207	1.14	05/03/2021	
21-04-00778-043	142.1-84	04/01/2021	ROOM B206	2.03	05/03/2021	
21-04-00778-044	142.1-85	04/01/2021	MENS ROOM	1.67	05/03/2021	
21-04-00778-045	142.1-86	04/01/2021	MENS ROOM LEFT SINK	27.6	04/28/2021	
21-04-00778-046	142.1-88	04/01/2021	WOMENS ROOM LEFT SINK	1.28	05/03/2021	
21-04-00778-047	142.1-89	04/01/2021	WOMENS ROOM RIGHT SINK	1.33	05/03/2021	
21-04-00778-048	142.1-91	04/01/2021	ROOM B217	10.8	05/03/2021	
21-04-00778-049	142.1-93	04/01/2021	ROOM B218	3.42	05/03/2021	
21-04-00778-050	142.1-95	04/01/2021	ROOM B219	36.6	05/03/2021	
21-04-00778-051	142.1-97	04/01/2021	ROOM B220	2.38	05/03/2021	
21-04-00778-052	142.1-99	04/01/2021	ROOM B221	48.2	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-053	142.1-101	04/01/2021	ROOM B222	39.1	05/03/2021	
21-04-00778-054	142.1-103	04/01/2021	ROOM B223	16.7	05/03/2021	
21-04-00778-055	142.1-105	04/01/2021	ROOM B224	21.7	05/03/2021	
21-04-00778-056	142.1-106	04/01/2021	BOYS BATHROOM LEFT SINK	1.80	05/03/2021	
21-04-00778-057	142.1-107	04/01/2021	BOYS BATHROOM CENTER SINK	21.5	05/03/2021	
21-04-00778-058	142.1-108	04/01/2021	BOYS BATHROOM RIGHT SINK	3.22	05/03/2021	
21-04-00778-059	142.1-110	04/01/2021	GIRLS BATHROOM LEFT SINK	12.3	05/03/2021	
21-04-00778-060	142.1-111	04/01/2021	GIRLS BATHROOM CENTER SINK	4.83	05/03/2021	
21-04-00778-061	142.1-112	04/01/2021	GIRLS BATHROOM RIGHT SINK	4.99	05/03/2021	
21-04-00778-062	142.1-114	04/01/2021	ROOM B232	15.7	05/03/2021	
21-04-00778-063	142.1-116	04/01/2021	ROOM B233	1.44	05/03/2021	
21-04-00778-064	142.1-117	04/01/2021	ROOM B235	<1.00	05/03/2021	
21-04-00778-065	142.1-118	04/01/2021	ROOM B235	1.56	05/03/2021	
21-04-00778-066	142.1-120	04/01/2021	ROOM B237	16.0	05/03/2021	
21-04-00778-067	142.1-122	04/01/2021	ROOM B238	18.9	05/03/2021	
21-04-00778-068	142.1-127	04/01/2021	ROOM B242	2.88	05/03/2021	
21-04-00778-069	142.1-129	04/01/2021	ROOM B243	1.53	05/03/2021	
21-04-00778-070	142.1-131	04/01/2021	ROOM B245	2.52	05/03/2021	
21-04-00778-071	142.1-133	04/01/2021	ROOM B247	4.36	05/03/2021	
21-04-00778-072	142.1-135	04/01/2021	ROOM B248	2.14	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980
 Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
 Erie St; Mayville, NY 14757

Report Number: 21-04-00778

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-073	142.1-137	04/01/2021	ROOM B253	1.25	05/03/2021	
21-04-00778-074	142.1-139	04/01/2021	MENS ROOM LEFT SINK	8.78	05/03/2021	
21-04-00778-075	142.1-140	04/01/2021	MENS ROOM RIGHT SINK	2.12	05/03/2021	
21-04-00778-076	142.1-142	04/01/2021	WOMENS ROOM LEFT SINK	3.01	05/03/2021	
21-04-00778-077	142.1-143	04/01/2021	WOMENS ROOM RIGHT SINK	6.35	05/03/2021	
21-04-00778-078	142.1-145	04/01/2021	ROOM B110	3.60	05/03/2021	
21-04-00778-079	142.1-147	04/01/2021	ROOM B117	2.40	05/03/2021	
21-04-00778-080	142.1-149	04/01/2021	ROOM B119	1.83	05/03/2021	
21-04-00778-081	142.1-151	04/01/2021	ROOM B118	3.03	05/03/2021	
21-04-00778-082	142.1-153	04/01/2021	ROOM B120	2.46	05/03/2021	
21-04-00778-083	142.1-154	04/01/2021	ROOM B122	<1.00	05/03/2021	
21-04-00778-084	142.1-155	04/01/2021	ROOM B122	5.78	05/03/2021	
21-04-00778-085	142.1-157	04/01/2021	ROOM B124	3.57	05/03/2021	
21-04-00778-086	142.1-158	04/01/2021	ROOM B125	2.41	05/03/2021	
21-04-00778-087	142.1-159	04/01/2021	BOYS BATHROOM LEFT SINK	1.47	05/03/2021	
21-04-00778-088	142.1-160	04/01/2021	BOYS BATHROOM CENTER SINK	1.22	05/03/2021	
21-04-00778-089	142.1-161	04/01/2021	BOYS BATHROOM RIGHT SINK	5.95	05/03/2021	
21-04-00778-090	142.1-162B	04/01/2021	BOTTLE FILL	<1.00	05/03/2021	
21-04-00778-091	142.1-163	04/01/2021	GIRLS BATHROOM LEFT SINK	5.75	05/03/2021	
21-04-00778-092	142.1-164	04/01/2021	GIRLS BATHROOM LEFT CENTER SINK	1.51	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-093	142.1-165	04/01/2021	GIRLS BATHROOM RIGHT CENTER SINK	1.76	05/03/2021	
21-04-00778-094	142.1-166	04/01/2021	GIRLS BATHROOM RIGHT SINK	1.14	05/03/2021	
21-04-00778-095	142.1-168	04/01/2021	ROOM B132	6.49	05/03/2021	
21-04-00778-096	142.1-170	04/01/2021	ROOM B133	3.33	05/03/2021	
21-04-00778-097	142.1-172	04/01/2021	ROOM B135	5.35	05/03/2021	
21-04-00778-098	142.1-173	04/01/2021	ROOM B137 LEFT SINK	36.2	05/03/2021	
21-04-00778-099	142.1-174	04/01/2021	ROOM B137 CENTER SINK	2.55	05/03/2021	
21-04-00778-100	142.1-175	04/01/2021	ROOM B137 RIGHT SINK	4.50	05/03/2021	
21-04-00778-101	142.1-177	04/01/2021	ROOM B138	3.87	05/03/2021	
21-04-00778-102	142.1-180	04/01/2021	ROOM B142	1.19	05/03/2021	
21-04-00778-103	142.1-182	04/01/2021	ROOM B143	2.54	05/03/2021	
21-04-00778-104	142.1-184	04/01/2021	ROOM B145	3.99	05/03/2021	
21-04-00778-105	142.1-185	04/01/2021	ROOM B147	<1.00	05/03/2021	
21-04-00778-106	142.1-186	04/01/2021	ROOM B147	2.87	05/03/2021	
21-04-00778-107	142.1-187	04/01/2021	ROOM B148	<1.00	05/03/2021	
21-04-00778-108	142.1-188	04/01/2021	ROOM B148	4.24	05/03/2021	
21-04-00778-109	142.1-190	04/01/2021	ROOM B154	4.05	05/03/2021	
21-04-00778-110	142.1-191	04/01/2021	ROOM B153 LEFT SINK	2.47	05/03/2021	
21-04-00778-111	142.1-192	04/01/2021	ROOM B153 RIGHT SINK	3.10	05/03/2021	
21-04-00778-112	142.1-196	04/01/2021	GIRLS LOCKER ROOM LEFT SINK	5.00	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-113	142.1-197	04/01/2021	GIRLS LOCKER ROOM RIGHT SINK	6.36	05/03/2021	
21-04-00778-114	142.1-198	04/01/2021	BOYS LOCKER ROOM LEFT SINK	3.22	05/03/2021	
21-04-00778-115	142.1-199	04/01/2021	BOYS LOCKER ROOM RIGHT SINK	4.58	05/03/2021	
21-04-00778-116	142.1-201	04/01/2021	ROOM A146	7.36	05/03/2021	
21-04-00778-117	142.1-202	04/01/2021	BOYS RESTROOM LEFT SINK	2.85	05/03/2021	
21-04-00778-118	142.1-203	04/01/2021	BOYS RESTROOM LEFT CENTER SINK	4.78	05/03/2021	
21-04-00778-119	142.1-204	04/01/2021	BOYS RESTROOM RIGHT CENTER SINK	1.77	05/03/2021	
21-04-00778-120	142.1-205	04/01/2021	BOYS RESTROOM RIGHT SINK	1.05	05/03/2021	
21-04-00778-121	142.1-206	04/01/2021	GIRLS BATHROOM LEFT SINK	2.47	05/03/2021	
21-04-00778-122	142.1-207	04/01/2021	GIRLS BATHROOM LEFT CENTER SINK	1.59	05/03/2021	
21-04-00778-123	142.1-208	04/01/2021	GIRLS BATHROOM RIGHT CENTER SINK	1.10	05/03/2021	
21-04-00778-124	142.1-209	04/01/2021	GIRLS BATHROOM RIGHT SINK	2.56	05/03/2021	
21-04-00778-125	142.1-210B	04/01/2021	BOTTLE FILL OUTSIDE ROOM A138	<1.00	05/03/2021	
21-04-00778-126	142.1-211	04/01/2021	ROOM A138 LEFT SINK LEFT FAUCET	13.8	05/03/2021	
21-04-00778-127	142.1-212	04/01/2021	ROOM A138 LEFT SINK RIGHT FAUCET	10.1	05/03/2021	
21-04-00778-128	142.1-213	04/01/2021	ROOM A138 SMALL SINK	28.9	05/03/2021	
21-04-00778-129	142.1-215	04/01/2021	ROOM A138 BATHROOM	2.26	05/03/2021	
21-04-00778-130	142.1-216	04/01/2021	KITCHEN FOOD PREP SINK	3.68	05/03/2021	
21-04-00778-131	142.1-217	04/01/2021	KITCHEN FOOD PREP SPRAYER	5.76	05/03/2021	
21-04-00778-132	142.1-218	04/01/2021	KITCHEN HAND WASHING SINK	10.6	05/03/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-133	142.1-219	04/01/2021	KITCHEN A135A	7.59	05/03/2021	
21-04-00778-134	142.1-220	04/01/2021	KITCHEN POT FILL RIGHT	3.20	05/03/2021	
21-04-00778-135	142.1-221	04/01/2021	KITCHEN POT FILL LEFT	6.13	05/03/2021	
21-04-00778-136	142.1-223	04/01/2021	KITCHEN HAND WASHING SINK NEAR STOVE	10.7	05/04/2021	
21-04-00778-137	142.1-224	04/01/2021	KITCHEN SINK NEAR STOVE	9.66	05/04/2021	
21-04-00778-138	142.1-225	04/01/2021	KITCHEN DISHWASHER SPRAYER	<1.00	05/04/2021	
21-04-00778-139	142.1-226	04/01/2021	KITCHEN DISHWASHER LEFT SINK	32.3	05/04/2021	
21-04-00778-140	142.1-227	04/01/2021	KITCHEN DISHWASHER LEFT SINK	12.2	05/04/2021	
21-04-00778-141	142.1-228	04/01/2021	KITCHEN HAND WASHING SINK NEAR DISHWASHER	13.3	05/04/2021	
21-04-00778-142	142.1-231	04/01/2021	GIRLS LOCKER ROOM CENTER SINK	2.28	05/04/2021	
21-04-00778-143	142.1-232	04/01/2021	GIRLS LOCKER ROOM RIGHT SINK	4.00	05/04/2021	
21-04-00778-144	142.1-234	04/01/2021	GIRLS COACH ROOM	10.2	05/04/2021	
21-04-00778-145	142.1-235B	04/01/2021	BOTTLE FILL LEFT	<1.00	05/04/2021	
21-04-00778-146	142.1-237	04/01/2021	BOYS LOCKER ROOM LEFT SINK	6.52	05/04/2021	
21-04-00778-147	142.1-238	04/01/2021	BOYS LOCKER ROOM CENTER SINK	46.7	05/04/2021	
21-04-00778-148	142.1-239	04/01/2021	BOYS LOCKER ROOM RIGHT SINK	14.9	05/04/2021	
21-04-00778-149	142.1-241	04/01/2021	SHOP CLASS LEFT SINK	1.25	05/04/2021	
21-04-00778-150	142.1-242	04/01/2021	SHOP CLASS CENTER SINK	9.75	05/04/2021	
21-04-00778-151	142.1-243	04/01/2021	SHOP CLASS RIGHT SINK	7.08	05/04/2021	
21-04-00778-152	142.1-244	04/01/2021	A111C	11.9	05/04/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-04-00778

Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
Erie St; Mayville, NY 14757

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-153	142.1-245	04/01/2021	A111B	5.63	05/04/2021	
21-04-00778-154	142.1-247	04/01/2021	BOYS POOL LOCKER ROOM	10.0	05/04/2021	
21-04-00778-155	142.1-248	04/01/2021	BOYS POOL LOCKER ROOM	6.86	05/04/2021	
21-04-00778-156	142.1-251	04/01/2021	GIRLS POOL LOCKER ROOM LEFT SINK	4.51	05/04/2021	
21-04-00778-157	142.1-252	04/01/2021	GIRLS POOL LOCKER ROOM RIGHT SINK	11.8	05/04/2021	
21-04-00778-158	142.1-254	04/01/2021	FOOTBALL LOCKER ROOM	3.84	05/04/2021	
21-04-00778-159	142.1-255	04/01/2021	FOOTBALL LOCKER ROOM	7.75	05/04/2021	
21-04-00778-160	142.1-258	04/01/2021	BOYS LOCKER ROOM LEFT SINK	16.0	05/04/2021	
21-04-00778-161	142.1-259	04/01/2021	BOYS LOCKER ROOM RIGHT SINK	10.2	05/04/2021	
21-04-00778-162	142.1-260	04/01/2021	GIRLS LOCKER ROOM LEFT SINK	3.25	05/04/2021	
21-04-00778-163	142.1-261	04/01/2021	GIRLS LOCKER ROOM RIGHT SINK	<1.00	05/04/2021	
21-04-00778-164	142.1-265	04/01/2021	ICE MACHINE	16.2	04/28/2021	
21-04-00778-165	142.1-290	04/01/2021	ROOM C153 LEFT SINK	1.79	05/04/2021	
21-04-00778-166	142.1-291	04/01/2021	ROOM C153 RIGHT SINK	1.28	05/04/2021	
21-04-00778-167	142.1-292	04/01/2021	RESTROOM	1.23	05/04/2021	
21-04-00778-168	142.1-299	04/01/2021	GIRLS BATHROOM LEFT SINK	<1.00	05/04/2021	
21-04-00778-169	142.1-300	04/01/2021	GIRLS BATHROOM LEFT CENTER SINK	17.6	05/04/2021	
21-04-00778-170	142.1-301	04/01/2021	GIRLS BATHROOM RIGHT CENTER SINK	2.92	05/04/2021	
21-04-00778-171	142.1-302	04/01/2021	GIRLS BATHROOM RIGHT SINK	1.28	05/04/2021	
21-04-00778-172	142.1-303B	04/01/2021	BOTTLE FILL	<1.00	05/04/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980
 Project/Test Address: 2020L-142.1; Chautauqua Lake School Building; 100 N
 Erie St; Mayville, NY 14757

Report Number: 21-04-00778

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-00778-173	142.1-304	04/01/2021	BOYS BATHROOM LEFT SINK	3.57	05/04/2021	
21-04-00778-174	142.1-305	04/01/2021	BOYS BATHROOM CENTER SINK	1.09	05/04/2021	
21-04-00778-175	142.1-306	04/01/2021	BOYS BATHROOM RIGHT SINK	2.45	05/04/2021	
21-04-00778-176	142.1-307	04/01/2021	ROOM C122	2.64	05/04/2021	
21-04-00778-177	142.1-310	04/01/2021	ROOM C118	3.05	05/04/2021	
21-04-00778-178	142.1-311	04/01/2021	ROOM C110	2.43	05/04/2021	
21-04-00778-179	142.1-312	04/01/2021	WOMENS ROOM LEFT SINK	19.2	05/04/2021	
21-04-00778-180	142.1-313	04/01/2021	WOMENS ROOM RIGHT SINK	<1.00	05/04/2021	
21-04-00778-181	142.1-315	04/01/2021	MENS ROOM LEFT SINK	1.39	05/04/2021	
21-04-00778-182	142.1-329	04/01/2021	C210 ALL GENDER BATHROOM	1.49	05/04/2021	
21-04-00778-183	142.1-330	04/01/2021	MENS ROOM RIGHT SINK	2.61	05/04/2021	

Method: EPA 200.8
 Analyst: Anthony Dee
 Accreditation #: NY 11714

Reviewed By Authorized Signatory: *Melissa Kanode*

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2022
Issued April 01, 2021
Revised April 02, 2021

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the
National Environmental Laboratory Accreditation Conference Standards (2016) for the category
ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Arsenic, Total	EPA 200.8 Rev. 5.4
Copper, Total	SM 19, 21-23 3113B (-04,-10) EPA 200.8 Rev. 5.4
Lead, Total	SM 19, 21-23 3113B (-04,-10) EPA 200.8 Rev. 5.4
Manganese, Total	EPA 200.8 Rev. 5.4

NEW YORK
Department
of Health

Serial No.: 63485

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.



1.6 Chains of Custody



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-4	Room 266 - Kitchen Sink	S	23:00
142.1-5	Room 268 - Left Sink	S	23:01
142.1-6	Room 268 - Right Sink	S	23:02
142.1-7	Faculty restroom - All gender bathroom	S	23:03
142.1-10	Girls bathroom - Left Sink	S	23:04
142.1-11	Girls bathroom - Center Left Sink	S	23:05
142.1-12	Girls bathroom - Center Right Sink	S	23:06
142.1-13	Girls bathroom - Right Sink	S	23:07
142.1-15	Boys bathroom - Left sink	S	23:08
142.1-16	Boys bathroom - Center Sink	S	23:09
142.1-17	Boys bathroom - Right Sink	S	23:10
142.1-18	Room 224 - Island Sink	S	23:11
142.1-19	Room 224 - Left Sink	S	23:12
142.1-20	Room 224 - Center Sink	S	23:13
142.1-21	Room 224 - Right Sink	S	23:14
142.1-22	Girls bathroom - Left Sink	S	23:15
142.1-23	Girls bathroom - Right Sink	S	23:16
142.1-24B	Bottle Filler	DFB	23:17

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

☒ If checked, also e-mail results to:

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Andrew Theal Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: E. Henderson Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): KTHARRIS Kellars Date: 4/6/21 Time: 11:55 AM

Sample Login (Name / Lab): Tasha Date: 4/27/21 4:45

Analysis (Name / Lab): Joey Oae Date: 5/4/21 2:07

QA/QC Review (Name / Lab): Melissa Date: 5/14/21 4:00

Archived / Released: QA/QC InterLAB Use: Date:

21-04-00778



Due Date:
05/04/2021
(Tuesday)
AE

Stohl

ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time
142.1-25	Boys bathroom	S	23:11
142.1-26	Boys bathroom	S	23:11
142.1-29	Room 206 - Small Room	S	23:20
142.1-30	Room 207 - Wall Sink	S	23:20
142.1-43	Room 208 - Small room	S	23:22
142.1-44	Room 208 - Wall sink	S	23:22
142.1-61	Room C 210 - Left sink	S	23:23
142.1-62	Room C 210 - Right sink	S	23:24
142.1-63	Room A201E	S	23:25
142.1-63B	Room A201E - Sink bottle filler	S	23:26
142.1-65	Men's room - Left sink	DFB	23:27
142.1-66	Men's room - Center sink	S	23:28
142.1-67	Men's room - Right sink	S	23:29
142.1-68	Women's room - Left sink	S	23:30
142.1-69	Women's room - Center sink	S	23:31
142.1-70	Women's room - Right sink	S	23:32
142.1-72	Room A217 - Bathroom	S	23:33
142.1-73	Room A217 - Sink	S	23:34
		S	23:35

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name

Stohl Env: Andrew Theal

Date: 4/1/2021

Relinquished By: E. Henderson Print Name

Stohl Env: Eric Henderson Jr.

Date: 4/2/2021

Received (Name / Lab): Eric Henderson

Date: 4-6-21

Time: 11:55 AM

Sample Login (Name / Lab): Trish

Date: 4/2/21

Time: 4:46

Analysis (Name / Lab): Eric Henderson

Date: 5/4/21

Time: 2:27 PM

QA/QC Review (Name / Lab): Michael

Date: 5/4/21

Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____

Date: _____

Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time
142.1-74	Room A217E - Sink	S	23:36
142.1-75	Room B210 - Left sink	S	23:37
142.1-76	Room B210 - Right sink	S	23:38
142.1-78	Room B209	S	23:39
142.1-80	Room B208	S	23:40
142.1-82	Room B207	S	23:41
142.1-84	Room B206	S	23:42
142.1-85	Men's room	S	23:43
142.1-86	Men's room - Left sink	S	23:44
142.1-88	Women's room - Left sink	S	23:45
142.1-89	Women's room - Right sink	S	23:46
142.1-91	Room B217	S	23:47
142.1-93	Room B218	S	23:48
142.1-95	Room B219	S	23:49
142.1-97	Room B220	S	23:50
142.1-99	Room B221	S	23:51
142.1-101	Room B222	S	23:52
142.1-103	Room B223	S	23:53

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name

Stohl Env: Andrew Theal

Date: 4/1/2021

Relinquished By: E. Henderson Jr. Print Name

Stohl Env: Eric Henderson Jr.

Date: 4/2/2021

Received (Name / Lab): OR Stevens

Date: 4/6/21

Time: 11:55 AM

Sample Login (Name / Lab): T. Stohl

Date: 4/22/21

Time: 5p

Analysis (Name / Lab): Stacy O'Neil

Date: 5/4/21

Time: 2:27 PM

QA/QC Review (Name / Lab): Melvin

Date: 5/4/21

Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____

Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-105	Room B224	S	23:54
142.1-106	Boys bathroom - Left sink	S	23:55
142.1-107	Boys bathroom - Center sink	S	23:56
142.1-108	Boys bathroom - Right sink	S	23:57
142.1-110	Girls bathroom - Left sink	S	23:58
142.1-111	Girls bathroom - Center sink	S	23:59
142.1-112	Girls bathroom - Right Sink	S	0:00
142.1-114	Room B232	S	0:01
142.1-116	Room B233	S	0:02
142.1-117	Room B235	B	0:03
142.1-118	Room B235	S	0:04
142.1-120	Room B 237	S	0:05
142.1-122	Room B238	S	0:06
142.1-127	Room B242	S	0:07
142.1-129	Room B243	S	0:08
142.1-131	Room B245	S	0:09
142.1-133	Room B247	S	0:10
142.1-135	Room B248	S	0:11

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: Eric Henderson Jr. Print Name Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): R. Blau Date: 4-6-21 Time: 11:55 AM

Sample Login (Name / Lab): T. Ashen Date: 4/27/21 Time: 3p

Analysis (Name / Lab): Gary O'Leary Date: 5/4/21 Time: 2:12 PM

QA/QC Review (Name / Lab): Michael Date: 5/4/21 Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-137	Room B253	S	0:12
142.1-139	Men's room - Left sink	S	0:13
142.1-140	Men's room - Right Sink	S	0:14
142.1-142	Women's room - Left sink	S	0:15
142.1-143	Women's room - Right Sink	S	0:16
142.1-145	Room B110	S	0:17
142.1-147	Room B117	S	0:18
142.1-149	Room B119	S	0:19
142.1-151	Room B118	S	0:20
142.1-153	Room B120	S	0:21
142.1-154	room B122	B	0:22
142.1-155	room B122	S	0:23
142.1-157	Room B124	S	0:24
142.1-158	Room B125	S	0:25
142.1-159	Boys bathroom - Left sink	S	0:26
142.1-160	Boys bathroom - Center sink	S	0:27
142.1-161	Boys bathroom - Right Sink	S	0:28
142.1-162B	Bottle Fill	DFB	0:29

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Andrew Theal Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): K. Haines Date: 4.6.21 Time: 11:55 am

Sample Login (Name / Lab): T. Haines Date: 4/27/21 Time: 5:00

Analysis (Name / Lab): George Ode Date: 5/14/21 Time: 8:27 am

QA/QC Review (Name / Lab): Kevin Date: 5/14/21 Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-163	Girls bathroom - Left sink	S	0:30
142.1-164	Girls bathroom - Left center sink	S	0:31
142.1-165	Girls bathroom - Right center sink	S	0:32
142.1-166	Girls bathroom - Right sink	S	0:33
142.1-168	Room B132	S	0:34
142.1-170	Room B133	S	0:35
142.1-172	Room B135	S	0:36
142.1-173	Room B137 - Left sink	B	0:37
142.1-174	Room B137 - Center sink	S	0:38
142.1-175	Room B137 - Right sink	S	0:39
142.1-177	Room B138	S	0:40
142.1-180	Room B142	S	0:41
142.1-182	Room B143	S	0:42
142.1-184	Room B145	S	0:43
142.1-185	Room B147	B	0:44
142.1-186	Room B147	S	0:45
142.1-187	Room B148	B	0:46
142.1-188	Room B148	S	0:47

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name

Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: E. Henderson Print Name

Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): Al Olivas

Date: 4-6-21 Time: 11:55 am

Sample Login (Name / Lab): T. Hahn

Date: 4/27/21 Time: 5p

Analysis (Name / Lab): Sony Ode

Date: 5/4/21 Time: 2:27 pm

QA/QC Review (Name / Lab): M. Hahn

Date: 5/4/21 Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____

Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLNENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-190	Room B154	S	0:48
142.1-191	Room B153 - Left sink	S	0:49
142.1-192	Room B153 - Right sink	S	0:50
142.1-196	Girls locker room - Left sink	S	0:51
142.1-197	Girls locker room - Right sink	S	0:52
142.1-198	Boys locker room - Left sink	S	0:53
142.1-199	Boys locker room - Right sink	S	0:54
142.1-201	Room A146	S	0:55
142.1-202	Boys restroom - Left sink	S	0:56
142.1-203	Boys restroom - Left center sink	S	0:57
142.1-204	Boys restroom - Right center sink	S	0:58
142.1-205	Boys restroom - Right sink	S	0:59
142.1-206	Girls bathroom - Left sink	S	1:00
142.1-207	Girls bathroom - Left center sink	S	1:01
142.1-208	Girls bathroom - Right center sink	S	1:02
142.1-209	Girls bathroom - Right sink	S	1:03
142.1-210B	Bottle fill - Outside room A138	DFB	1:04
142.1-211	Room A138 - Left sink left faucet	S	1:05

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Andrew Theal Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: E. Henderson Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): R. Plummer Date: 4-6-21 Time: 11:55 AM

Sample Login (Name / Lab): T. Shuman Date: 4/2/21 Time: 5:15p

Analysis (Name / Lab): Yang, Oca Date: 5/4/21 Time: 2:27 AM

QA/QC Review (Name / Lab): Michael Date: 5/4/21 Time: 4pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-212	Room A138 - Left sink right faucet	S	1:06
142.1-213	Room A138 - Small sink	S	1:07
142.1-215	Room A138 - Bathroom	S	1:08
142.1-216	Kitchen - Food prep sink	S	1:09
142.1-217	Kitchen - Food prep sprayer	S	1:10
142.1-218	Kitchen - Hand washing sink	S	1:11
142.1-219	Kitchen - A135A	S	1:12
142.1-220	Kitchen - Pot fill right	S	1:13
142.1-221	Kitchen - Pot fill left	S	1:14
142.1-223	Kitchen - Hand washing sink near stove	S	1:15
142.1-224	Kitchen - Sink near stove	S	1:16
142.1-225	Kitchen - Dishwasher sprayer	S	1:17
142.1-226	Kitchen - Dishwasher left sink	S	1:18
142.1-227	Kitchen - Dishwasher left sink	S	1:19
142.1-228	Kitchen - Hand washing sink near dishwasher	S	1:20
142.1-231	Girls locker room - Center sink	S	1:22
142.1-232	Girls locker room - Right sink	S	1:23
142.1-234	Girls coach room	S	1:24

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

Ehenderson@StohlEnv.com

Sampled By: <u>Andrew Theal</u>	Print Name	Stohl Env: <u>Andrew Theal</u>	Date: <u>4/1/2021</u>
Relinquished By: <u>Eric Henderson Jr.</u>	Print Name	Stohl Env: <u>Eric Henderson Jr.</u>	Date: <u>4/2/2021</u>
Received (Name / Lab): <u>Pat Quinn</u>		Date: <u>4.6.21</u>	Time: <u>11:55 AM</u>
Sample Login (Name / Lab): <u>Tasha</u>		Date: <u>4/2/21</u>	Time: <u>5:16</u>
Analysis (Name / Lab): <u>Gary O'Connell</u>		Date: <u>5/4/21</u>	Time: <u>2:27 PM</u>
QA/QC Review (Name / Lab): <u>Mimi</u>		Date: <u>5/4/21</u>	Time: <u>9 AM</u>
Archived / Released: _____	QA/QC InterLAB Use: _____	Date: _____	Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-235B	Bottle fill - Left	DFB	1:25
142.1-237	Boys locker room - Left sink	S	1:26
142.1-238	Boys locker room - Center sink	S	1:27
142.1-239	Boys locker room - Right sink	S	1:28
142.1-241	Shop class - Left sink	S	1:29
142.1-242	Shop class - Center sink	S	1:30
142.1-243	Shop class - Right sink	S	1:31
142.1-244	A111c	S	1:32
142.1-245	A111B	S	1:33
142.1-247	Boys pool locker room	S	1:34
142.1-248	Boys pool locker room	S	1:35
142.1-251	Girls pool locker room - Left sink	S	1:37
142.1-252	Girls pool locker room - Right sink	S	1:38
142.1-254	Football locker room	S	1:40
142.1-255	Football locker room	S	1:41
142.1-258	Boys locker room - Left sink	S	1:43
142.1-259	Boys locker room - Right sink	S	1:44
142.1-260	Girls locker room - Left sink	S	1:45

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Andrew Theal Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: E. Henderson Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): A. Theal Date: 4/6/21 Time: 11:55 AM

Sample Login (Name / Lab): T. Shahan Date: 4/27/21 Time: 5:15

Analysis (Name / Lab): Samy Oda Date: 4/27/21 Time: 2:12 PM

QA/QC Review (Name / Lab): M. M. M. Date: 5/4/21 Time: 4:00 PM

Archived / Released: QA/QC InterLAB Use: Date: Time:



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-142.1

Client: Chautauqua Lake CSD

Contact: Pat Quinn

Building: Chautauqua Lake School Building

Location: 100N Erie St, Mayville, NY 14757

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
142.1-261	Girls locker room - Right sink	S	1:46
142.1-265	Ice machine	IM	1:47
142.1-290	Room C153 - Left sink	S	1:49
142.1-291	Room C153 - Right sink	S	1:50
142.1-292	Restroom	S	1:51
142.1-299	Girls bathroom - Left sink	S	1:53
142.1-300	Girls bathroom - Left center sink	S	1:54
142.1-301	Girls bathroom - Right center sink	S	1:55
142.1-302	Girls bathroom - Right sink	S	1:56
142.303B	Bottle fill	DFB	1:56
142.1-304	Boys bathroom - Left sink	S	1:57
142.1-305	Boys bathroom - Center sink	S	1:58
142.1-306	Boys bathroom - Right sink	S	1:59
142.1-307	Room C122	S	2:00
142.1-310	Room C118	S	2:02
142.1-311	Room C110	S	2:03
142.1-312	Women's room - Left sink	S	2:04
142.1-313	Women's room - Right sink	S	2:05

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Andrew Theal Print Name Andrew Theal Stohl Env: Andrew Theal Date: 4/1/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 4/2/2021

Received (Name / Lab): OK Harris Date: 4.6.21 Time: 11:55 AM

Sample Login (Name / Lab): Stohl Date: 4/6/21 Time: 5:30

Analysis (Name / Lab): Yong Owe Date: 5/4/21 Time: 2:22 PM

QA/QC Review (Name / Lab): Mark Date: 5/4/21 Time: 4:00 PM

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

The logo for Stohl Environmental. The word "Stohl" is in a large, bold, green sans-serif font. A thin green swoosh underline starts under the 'S', goes under the 't', and then loops around the 'h' and 'l'. Below "Stohl", the word "ENVIRONMENTAL" is written in a smaller, blue, all-caps sans-serif font. A thin blue horizontal line is positioned below the word "ENVIRONMENTAL".

3860 California Road, Orchard Park, New York 14127

PHONE (716) 312-0070 FAX (716) 312-8092

WWW.STOHLENVIRONMENTAL.COM